

# Arm Attachment Bushing

## “Buddy Bushing”



Inner Bushing Rotates



*The new bushing increased the strength of the clevis attachment by up to 25%*

- Improves reliability
- Process improvement
- Simplification
- Extends hardware life
- Saves costs in transmission and distribution line repairs

### Problem:

Over time, wind-driven rubbing between line insulator hardware and the associated cross arm attachment points can cause failure of the cross arm at the point of attachment.



### Solution:

Stainless steel Buddy Bushing was designed to eliminate the sawing action that was causing the insulator attachment hole to fail by allowing the inner bushing to rotate.



1001 Webster Avenue  
Waco, TX 76706  
254-757-1177  
noahg@diversifiedproduct.com  
www.line-wise.com

**LineWise**  
by Diversified Products

INSPIRED BY LINEMEN TESTED BY LINEMEN TRUSTED BY LINEMEN

Photos and diagrams are for promotional purposes only.  
Product design and specifications may change without notice or obligation.

U.S. Patent No. 8,399,770B1

©2015 Diversified Products